Executive Registry

16 November 1953

Mr. Edward J. Kelly Superintendent, National Capital Parks Wetional Capital Park Service Department of Interior Room 1230, Interior Building Washington 25, D.C.

Dear Mr. Kelly:

Reference is made to recent discussions with Mr. Bartel of your office regarding the flooded conditions which are existent during inclement weather along the entire walkway in front of Tempo Buildings I, J, K, and L. These buildings are located to the south of the Reflection Pool.

A survey was made on 3 November 1973, by Mr. Bartel, Mr. R. J. Tompkins, Public Buildings Service Group Superintendent, and representatives of this office. The survey revealed conclusively that the trouble stems from depressions which exist in the paved walkway.

On rainy days the entire walkway is inundated between the entrance to Building "L" and the granite steps leading to Lincoln Memorial Circle. Numerous puddles are also present from the aforementioned entrance due east to the end of Building "I". The walkway becomes very hazardous during the winter season when melting snow and rain freeze on the pavement since moisture does not drain off properly.

Mr. Bartel indicated that arrangements will be made to clean debris from existing drains located at infrequent intervals along the walkway and replace damaged drain covers where necessary. This will, no doubt, alleviate the situation to a limited degree.

However, it is felt that the entire problem can only be solved by the application of "blacktop" over the present walkway. This procedure was used on the opposite side of the Reflection Pool with very gratifying results.

It is suggested that if blacktop surfacing was applied starting at the fence-line and feathered out to the center of the walkway, it would eliminate the undesirable conditions experienced during inclement weather.

BOX NO. FLD NO. DOC. NO. 2 NO CHARGE

Approved For Release 1999/08/27: CIA-RDP78-04718A000600250001-9

Mr. Edward J. Kelly

-2-

16 November 1953

It is urgently requested that every effort be made to remedy the above-mentioned conditions as soon as possible. We would appreciate an indication from your office relative to the corrective action which will be taken.

Very truly yours,

SIGNED

25X1A9a

Ministration.

Chief, General Services Office

GSO/SM&F/JDK:rk

Distribution:

2 - addressee

2 - Gen. Ser.

1 - chrono

1 - file 1 - A-DD/A

	CENTRAL INTELLIGENCE AGENCY	
	OFFICIAL ROUTING SLIP	}
	OFFICIAL ROUTING SERI	
 	A A WITIALS D	DATE
	Acting DD/A	
:		
	3	
,		
	; .	
FR	OM 25X1A6a INITIALS E	DATE
	Chief, GSO Rm. 138	/16/53
	3	
[APPROVAL INFORMATION SIGN	IATURE
] [ACTION DIRECT REPLY RETU	JRN
[COMMENT PREPARATION OF REPLY DISP	ATCH
[CONCURRENCE RECOMMENDATION FILE	
]	Remarks: This is to indicate that action have been taken as you requested in connection with the improper drainage of the walkway	2.5

Approved For Release 1999/08/27: CIA-RDP78-04718A00060025 0001-9 SECRET CONFIDENTIAL: RESTRICTED UNCLASSIFIED

FORM NO. 30-4